

TANK #30 & 8014 Acid Holding

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Normandie Torrance, CA 90502			A.State Manifest Document Number 84827633		B.State Generator's ID 64150	
4. Generator's Phone (213) 583-5677			6. US EPA ID Number C A D 0 5 8 0 1 8 3 6 7		C.State Transporter's ID 64150	
5. Transporter 1 Company Name J. C. Liquid Waste Disposal			8. US EPA ID Number		D.Transporter's Phone 213 268-3137	
7. Transporter 2 Company Name			10. US EPA ID Number		E.State Transporter's ID	
9. Designated Facility Name and Site Address IT COPR. 896 Waterbird Way Martinez, CA 94553			12.Containers No. Type		F.Transporter's Phone	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			13. Total Quantity		14. Unit Wt/Vol	
a. Waste Acid Liquid NOS Corrosive - NA 1760			001 TT 04500		G 111 D002	
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above Chromic Acid 0-14% Sulfuric Acid 0-14% Hydrofluoric Acid 0-14% Nitric Acid 0-14%			K.Handling Codes for Wastes Listed Above 08/15/06			
15. Special Handling Instructions and Additional Information Guide #60 Profile 4819 Use gloves, goggles, respirator - May cause severe burns to skin & eyes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Donald C. Gerber			Signature <i>Donald C. Gerber</i>		Date Month Day Year 05/15/86	
17. Transporter 1 Acknowledgement of Receipt of Materials			Printed/Typed Name 56091 Bill SRECKE		Signature <i>Bill Srecke</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials			Printed/Typed Name		Signature	
19. Discrepancy Indication Space Gerber 5-15-86 Section 7 : remaining as water per Donald			20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Date	
Printed/Typed Name Gregory Topor			Signature <i>Gregory Topor</i>		Month Day Year 05/15/86	

TANK #30 & 8014 Acid Holding

Department of Health Services
Toxic Substances Control Division
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No.	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Normandie Torrance, CA 90502			A.State Manifest Document Number 84827633			
4. Generator's Phone (213 583-6677			B.State Generator's ID			
5. Transporter 1 Company Name J. C. Liquid Waste Disposal		6. US EPA ID Number C A D 0 5 8 0 1 8 3 6 7		C.State Transporter's ID		
7. Transporter 2 Company Name		8. US EPA ID Number		D.Transporter's Phone 213 268-3137		
9. Designated Facility Name and Site Address IT COPR. 896 Waterbird Way Martinez, CA 94553		10. US EPA ID Number C A D 0 0 0 0 9 4 7 7 1		E.State Transporter's ID		
				F.Transporter's Phone		
				G.State Facility's ID		
				H.Facility's Phone		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12.Containers No.	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Acid Liquid NOS Corrosive - NA 1760			001	TT	04500	G 111 D002
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above Chronic Acid 0-14% Sulfuric Acid 0-14% Remaining Water Hydrofluoric Acid 0-14% Nitric Acid 0-14%			K.Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Guide #60 Profile 4819 Use gloves, goggles, respirator - May cause severe burns to skin & eyes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Donald C. Gerber			Signature <i>Donald C. Gerber</i>		Date Month Day Year 05 15 86	
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Bill Spruce</i>		Date Month Day Year 05 15 86	
Printed/Typed Name 56091			Signature <i>Bill Spruce</i>		Date Month Day Year 05 15 86	
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date Month Day Year	
Printed/Typed Name			Signature		Date Month Day Year	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name			Signature		Date Month Day Year	

YELLOW GENERATOR RETAINS